

Milling Sheet: Model (1)

Student Name:

Problem

Cutter	Workpiece	Operation & Cutting Conditions
<ul style="list-style-type: none">• Coated Carbide Inserts.• Cutter Diameter (Dc)=100 mm.• Teeth (inserts) Number (Z) = 20.• Cutter width (b) = 50 mm.	<ul style="list-style-type: none">• Hard Alloy Steel with Dimension (600×500×200) mm.• Removed thickness (h) = 13 mm.• Specific Energy (Ks):2000 kp/cm²	<ul style="list-style-type: none">• Type: Four Slots using single cutter.• Cutting Speed (Vc): 50 m/min.• Feed (fr) = 1.5 mm/rev.

Milling Sheet: Model (2)

Student Name:

Problem

• Cutter	•	• Conditions
<ul style="list-style-type: none">• Coated Carbide Inserts• Cutter Diameter (Dc)=150 mm.• Teeth (inserts) Number (Z) = 30.• Cutter width (b) = 10 mm.	<ul style="list-style-type: none">• Hard Alloy Steel• Removed thickness (h) = 13 mm.• Specific Energy (Ks):2000 kp/cm²	<ul style="list-style-type: none">• 20 slots on a cylindrical rod.• Cutting Speed (Vc): 50 m/min.• Feed = 0.2 mm/tooth

Milling Sheet: Model (3)

Student Name:

Problem

• Cutter	•	• Conditions
<ul style="list-style-type: none">• Coated Carbide Inserts (lovejoy)• Cutter Diameter (Dc)=150 mm.• Teeth (inserts) Number (Z) = 30.• Cutter width (b) = 30 mm.	<ul style="list-style-type: none">• Hard Alloy Steel• Removed thickness (h) = 13 mm.• Specific Energy (Ks):2000 kp/cm²	<ul style="list-style-type: none">• 3 slots using gang milling.• Cutting Speed (Vc): 50 m/min.• Feed = 25 mm/min.

Milling Sheet: Model (4)

Student Name:

Problem

• Cutter	•	• Conditions
<ul style="list-style-type: none">• Coated Carbide Inserts (lovejoy)• Cutter Diameter (Dc)=100 mm.• Teeth (inserts) Number (Z) = 20.• Cutter width (b) = 40 mm.	<ul style="list-style-type: none">• Hard Alloy Steel with dimension (600×300×200) mm.• Removed thickness (h) = 13 mm.• Specific Energy (Ks):2000 kp/cm²	<ul style="list-style-type: none">• Type: Slab milling• Cutting Speed (Vc): 50 m/min.• Feed = 0.12 mm/tooth.

Part (A) Operation Sketch



Part (B) Machining Time

Rough Machining Time (T_r) =

Finish machining Time (T_f) =

Machining Time (T) =

Total Machining Time (T_{tot}) =

Part (C) Cutting Forces and Power

Main Cutting Force $F_t =$

$$A_c =$$

$$\phi_s =$$

Total Main Cutting Force = $F_t \times Z_s =$

$$Z_s =$$

Radial Force Component (F_r) =

Axial Force Component (Fa)=

$$\begin{aligned} \text{Consumed Motor Power (P)} &= \text{Total Ft} \quad \times \quad \text{Cutting Speed (Vc)} \\ &= \quad \times \quad = \quad \text{kw} \end{aligned}$$

$$\begin{aligned} \text{Arbor Torque (Mt)} &= \text{Total Ft} \quad \times \quad \text{Dc/2} \\ &= \quad \times \quad = \quad \text{kp.m} \end{aligned}$$

Part (D) Load Curve



Surface signature			
Recommendation	Z=	Dc=	Dr=